











LACK OF APPR. RAIL ALONG WITH BLUNT TERMINUS
IS A TRAFFIC SAFETY HAZARD







































CURTIS



CIRKIS



Red graffiti on the railing, including the word 'CIRKIS' and a circular logo.

Red graffiti on the railing, including the word 'CIRKIS' and a circular logo.

Red graffiti on the railing, including the word 'CIRKIS' and a circular logo.

Red graffiti on the railing, including the word 'CIRKIS' and a circular logo.

Red graffiti on the railing, including the word 'CIRKIS' and a circular logo.





DECK HAS HIGH POTENTIAL FOR RANDOM FULL DEPTH FAILURES





0-2556

CURBIS

152+620

720W

100











50% OF BEARING #6 IS UNDERMINED DUE TO SEVERE SPALLING ALONG ABOUT. #2 BRIDGE SEAT





W 1 A
D 3 D



