

Bank erosion behind guard rail should be repaired in the north bound lane.

















