















CONCRETE BRIDGE SEAT BELOW BEAMS 2 AND 3  
HAS CRACKED THROUGH DUE TO ABOUT .1  
ROTATION TOWARDS THE CHANNEL









