

CONCRETE BRIDGE SEAT BELOW BEAMS 2 AND 3
HAS CRACKED THROUGH DUE TO ABOUT .1
ROTATION TOWARDS THE CHANNEL

