



ONE LANE
BRIDGE

12-0



SPEED
LIMIT
25













1872
QUEEN POST

SPEED LIMIT
HORSES AT A WALK
MOTOR VEHICLES
NO MORE THAN 10 MPH

NO
LOITERING







DOWNSTREAM LOWER CHORD LOCAL FAILURE
WITH LAG BOLTED ANGLE REPAIR

2-3/8"

FRACTURE OF INSIDE BEAM







































UNDERSIDE OF FRACTURED DOWNSTREAM
BOTTOM CHORD



