

ABUT#1 IS UNSTABLE  
THERE IS A LARGE SCOUR HOLE IN FRONT OF  
THE ABUTMENT.

