

6th knee brace missing on left side. at 12th vertical



ONE LANE  
BRIDGE

↑  
10'-6"  
↓

STOP













ONE LANE  
BRIDGE

↑  
10'-6"  
↓



Circa 1888  
**UNION VILLAGE BRIDGE**  
Restored 2002

YIELD















EST. 1868  
UNION VILLAGE BRIDGE  
RESTORED 2002

STOP

W  
S



5th knee brace missing at tenth vertical.  
vertical split out at knotch out.

left side





GE






collision damage at portal on abutment #2 left side











lag bolt loose at tie beam 3/4 inch.  
at the 18th vertical. right side.





crack inside brace at 8th vertical left side



UNION VILLAGE BRIDGE  
BUILT 1890

ONE LANE  
BRIDGE

10'-6"

STOP

