



lag bolt loose at tie beam 3/4 inch.
at the 18th vertical. right side.