

LONGITUDINAL CRACKS THROUGH OUTER ARCH RIB  
AT THE 6TH VERTICAL ALONG DOWNSTREAM SIDE  
NOTE CHALK MARKS IDENTIFYING LIMITS OF CRACK  
PROPAGATION

