

SHEAR FAILURE OF TENON AT TOP POST

THE POST HAS PUSHED TOWARDS
MIDSPAN IN REACTION OF THE
THRUST OF DIAG. BRACE

TIE BEAM

TOP CHORD

SHIPKNEE

POST

MIDSPAN

BRACE

NOTE: ALL CHECK BRACES AND MAIN BRACES
ARE SECURE AND IN PLACE

