

TYPICAL TENON FAILURE ALONG WITH MINOR
POST DROP AT INTERFACE WITH UPPER
CHORD

