



STATE OF VERMONT
 AGENCY OF TRANSPORTATION
 MATERIALS & RESEARCH SECTION
 SUBSURFACE INFORMATION

BORING LOG

FERRISBURGH
 NHG SGNL(42)
 US-7

Boring No.: **B-101**

Page No.: 1 of 1

Pin No.: 13B016

Checked By: MLM

Boring Crew: GARROW, JUDKINS
 Date Started: 5/08/13 Date Finished: 5/08/13
 VTSPG NAD83: N 622621.86 ft E 1444735.64 ft
 Station: 165+13 Offset: -18.50
 Ground Elevation: 228.0 ft

Type: WB SS
 I.D.: 4 in 1.5 in
 Hammer Wt: N.A. 140 lb.
 Hammer Fall: N.A. 30 in.
 Hammer/Rod Type: Auto/AWJ
 Rig: CME 55 TRACK C = 1.46

Groundwater Observations

Date	Depth (ft)	Notes
05/08/13	4.6	While drilling.

Depth (ft)	Strata (1)	CLASSIFICATION OF MATERIALS (Description)	Blows/6" (N Value)	Moisture Content %	Gravel %	Sand %	Fines %
		Asphalt Pavement, 0.0 ft - 0.7 ft					
		A-1-a, SaGr, gry, Dry, Rec. = 1.0 ft, Sample was mostly pulverized & broken rock.	13-30-21-21 (51)	1.4	68.2	23.4	8.4
		A-1-b, Sa, brn, Moist, Rec. = 0.9 ft	4-10-7-6 (17)	9.7	7.1	78.8	14.1
5		A-2-4, SiSa, brn, Moist, Rec. = 0.3 ft		15.5	17.7	51.9	30.4
		A-4, SaSi, brn, Moist, Rec. = 1.3 ft, Lab Note: A very thin layer of clay was noticeable.	4-1-5-11 (6)	12.4	19.3	39.3	41.4
		A-1-b, GrSa, brn, Wet, Rec. = 0.9 ft	2-2-7-11 (9)	14.1	37.5	51.0	11.5
10		A-2-4, GrSiSa, brn, MTW, Rec. = 1.3 ft	15-30-40-R (70)	9.4	26.1	41.7	32.2
		A-2-4, GrSiSa, brn, Moist, Rec. = 0.9 ft	30-R (R)	10.3	22.4	42.5	35.1
15		A-4, SaSi, brn-gry, Moist, Rec. = 0.8 ft	35-R (R)	12.9	13.0	28.5	58.5
20		Field Note: Cleaned out casing. Appears to be sandy silt					
		A-2-4, GrSiSa, gry, Moist, Rec. = 0.5 ft	45-R (R)	9.5	21.8	43.2	35.0
25		Field Note: NXDC, Boulder					
		A-2-4, SiSa, gry, MTW, Rec. = 1.1 ft	6-15-42-R (57)	16.2	11.6	66.8	21.6
		Hole stopped @ 26.8 ft					
		Remarks: Hole collapsed at 19.1 feet when casing was removed.					

Notes: 1. Stratification lines represent approximate boundary between material types. Transition may be gradual.
 2. N Values have not been corrected for hammer energy. C is the hammer energy correction factor.
 3. Water level readings have been made at times and under conditions stated. Fluctuations may occur due to other factors than those present at the time measurements were made.

BORING LOG 2 FERRISBURGH NHG SGNL(42).GPJ VERMONT AOT.GDT 5/23/13