

TOD Program Steps

-----

Step 5            Program 1            Step Begins    2200

Flash. . . . .	X	Dimming Enable. . . . .
Red Rest . . . . .	.	Alt Veh Extension . . . . .
Spare 5. . . . .	.	Det Log Enable. . . . .
Spare 3. . . . .	.	Spare 4 . . . . .
Type 0 Dly Enable. . . . .	.	Spare 2 . . . . .
Det Diag Plan. . . . .	0	

	Phase Number											
	1	2	3	4	5	6	7	8	9	10	11	12
Max 2 Enable . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Max 3 Enable . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Veh Recall . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Veh Max Recall . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Ped Recall . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Cond Service Inhibit. . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Phase Omit . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Special Function . . . . .	.	.	.	.	.	.	.	.	.	.	.	.

Alt Sequence . . . . .	A	B	C	D	E	F
------------------------	---	---	---	---	---	---

-----