

TOD Program Steps

-----

Step 7            Program 2            Step Begins    0000

Flash. . . . . X            Dimming Enable. . . . .  
 Red Rest . . . . .            Alt Veh Extension . . . . .  
 Spare 5. . . . .            Det Log Enable. . . . .  
 Spare 3. . . . .            Spare 4 . . . . .  
 Type 0 Dly Enable. . . . . Spare 2 . . . . .  
 Det Diag Plan. . . . . 0

	Phase Number											
	1	2	3	4	5	6	7	8	9	10	11	12
Max 2 Enable . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Max 3 Enable . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Veh Recall . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Veh Max Recall . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Ped Recall . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Cond Service Inhibit. . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Phase Omit . . . . .	.	.	.	.	.	.	.	.	.	.	.	.
Special Function . . . . .	.	.	.	.	.	.	.	.	.	.	.	.

	A	B	C	D	E	F
Alt Sequence . . . . .	.	.	.	.	.	.

-----