

TOD Program Steps

Step 5 Program 1 Step Begins 2200

Flash. . . . . X Dimming Enable. . . . .
Red Rest . . . . . Alt Veh Extension . . . . .
Spare 5. . . . . Det Log Enable. . . . .
Spare 3. . . . . Spare 4 . . . . .
Type 0 Dly Enable. . . Spare 2 . . . . .
Det Diag Plan. . . . 0

Phase Number
1 2 3 4 5 6 7 8 9 10 11 12
Max 2 Enable . . . . .
Max 3 Enable . . . . .
Veh Recall . . . . .
Veh Max Recall . . . . .
Ped Recall . . . . .
Cond Service Inhibit. . . . .
Phase Omit . . . . .
Special Function . . . . .

Alt Sequence . . . . . A B C D E F

Step 6 Program 1 Step Begins 0000

Flash. . . . . X Dimming Enable. . . . .
Red Rest . . . . . Alt Veh Extension . . . . .
Spare 5. . . . . Det Log Enable. . . . .
Spare 3. . . . . Spare 4 . . . . .
Type 0 Dly Enable. . . Spare 2 . . . . .
Det Diag Plan. . . . 0

Phase Number
1 2 3 4 5 6 7 8 9 10 11 12
Max 2 Enable . . . . .
Max 3 Enable . . . . .
Veh Recall . . . . .
Veh Max Recall . . . . .
Ped Recall . . . . .
Cond Service Inhibit. . . . .
Phase Omit . . . . .
Special Function . . . . .

Alt Sequence . . . . . A B C D E F