

**CAUTION**  
DANGEROUS VOLTAGES EXIST IN THIS CABINET. ALL SERVICE OR ADJUSTMENTS MUST BE DONE BY QUALIFIED PERSONNEL FOR PROPER AND SAFE OPERATION OF THIS CONTROLLER. PERIODIC MAINTENANCE IS REQUIRED TO INSURE TO THE RESPECTABLE SERVICE RECORDS FOR PERIODIC MAINTENANCE AND ADJUSTMENT PROCEDURES.  
THIS CONTROLLER IS EQUIPPED WITH A CONFLICT MONITOR. INTERLOCKED TO PREVENT AUTOMATIC OPERATION WHEN THE CONFLICT MONITOR IS REMOVED. DO NOT DELAY OR REMOVE THE CONFLICT MONITOR.  
CHECK FOR PROPER OPERATION OF THIS CONFLICT MONITOR AT THE TIME OF INSTALLATION AND AT LEAST EVERY 6 MONTHS, THEREAFTER.

TESI Traffic Engineering And Control, Inc.  
175 1st St. Cambridge, MA 02142  
TEL: 617/761-7444  
FAX: 617/761-7444  
LOCATION: \_\_\_\_\_  
CITY: \_\_\_\_\_ STATE: \_\_\_\_\_

TURN-ON  
5/12/94  
11:30 AM

Fuses in pole for  
Cabinet

01	05	01	05
02	06	02	06
03	07	03	07
04	08	04	08
SYSTEM	TIME CLOCK	SYSTEM	TIME CLOCK
AUX. FLASH	LOC. TEST	AUX. FLASH	LOC. TEST

