



## **Route Log Progress Chart**

**DISTRICT TOWN DRAFT** Please Note: Errors and Omissions May Exist. ETE I-91







DESCRIPT	TANI.	DI C	$\mathbf{N}$
DESCRIPI	TOIA	DL	ノしト

Bridge 14N: Stringer/multi-beam or girder - 1961 Structure No. 200091014N13132 Length: 243' Width: 30.0' Facility Carried: I 00091 ML Bridge Type: 3 SPAN ROLLED BEAM Features Intersected: SACKETTS BROOK Surface: Bituminous Maintenance/Ownership: State

Culvert 14-1: Culvert - 1961 Structure No. 30009114-113131 Length: 10' Under Clearance: 5.0' Facility Carried: 191 Bridge Type: RC BOX Features Intersected: BROOK Maintenance: State

Stringer/multi-beam or girder - 1961 Structure No. 200091015N13132 Length: 299' Width: 30.0' Under Clearance: 16.42' Facility Carried: I 00091 ML Bridge Type: 5 SPAN ROLLED BEAM Features Intersected: I 91 OVER TH NO 3 Surface: Bituminous Maintenance/Ownership: State

Bridge 16N: Stringer/multi-beam or girder - 1961 Structure No. 200091016N13132 Length: 356' Width: 30.0' Under Clearance: 53.0' Facility Carried: I 00091 ML Bridge Type: 4 SPAN ROLLED BEAM Features Intersected: I 91 OVER TH 50 PUT B Surface: Bituminous Maintenance/Ownership: State

Culvert 17-2: Culvert - 1962 Structure No. 30009117-213131 Length: 10' Under Clearance: 8.0' Facility Carried: 191 Bridge Type: RC BOX Features Intersected: BROOK Maintenance: State

Culvert 17-3: Culvert - 1962 Structure No. 30009117-313201 Length: 10' Under Clearance: 8.0' Facility Carried: 191 Bridge Type: RC BOX Features Intersected: BROOK Maintenance: State

Stringer/multi-beam or girder - 1962 Structure No. 200091018N13202 Length: 133' Width: 42.0' Under Clearance: 17.5' Facility Carried: I 00091 ML Bridge Type: 3 SPAN ROLLED BEAM Features Intersected: I 91 OVER TH NO 52 Surface: Bituminous Maintenance/Ownership: State

Culvert 18-1: Culvert - 1963 Structure No. 30009118-113201 Length: 12' Under Clearance: 10.0' Facility Carried: 191 Bridge Type: RC BOX Features Intersected: BROOK Maintenance: State