



Route Log Progress Chart

DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Unit with questions or concerns. **DISTRICT ROUTE TOWN ANDOVER** VT-11





DESCR	RIPT	ION	BLO	Ck

Bridge <mark>35</mark>: Slab - 1929 Structure No. 200016003514012 Length: 28' Width: 29.2' Facility Carried: VT 00011 ML Bridge Type: CONCRETE SLAB Features Intersected: MID. BR WILLIAMS RIVER Surface: Bituminous Maintenance/Ownership: State

Bridge <mark>36</mark>: Tee Beam - 1929 Structure No. 200016003614012 Length: 28' Facility Carried: VT 00011 ML Bridge Type: TBEAM WIDE W/ STL BM Features Intersected: MID. BR WILLIAMS RIVER Surface: Bituminous Maintenance/Ownership: State

Stringer/multi-beam or girder - 1929 Structure No. 200016003714012 Length: 60' Width: 29.2' Facility Carried: VT 00011 ML Bridge Type: ROLLED BEAM Features Intersected: MID. BR WILLIAMS RIVER Surface: Bituminous Maintenance/Ownership: State

Bridge <mark>38</mark>: Tee Beam - 1929 Structure No. 200016003814012 Length: 33' Width: 29.3' Facility Carried: VT 00011 ML Bridge Type: TBEAM WIDE W/ STL BM Features Intersected: MID. BR WILLIAMS RIVER Surface: Bituminous Maintenance/Ownership: State

Stringer/multi-beam or girder - 1929 Structure No. 200016003914012 Length: 46' Width: 29.4' Facility Carried: VT 00011 ML Bridge Type: ROLLED BEAM Features Intersected: MID. BR WILLIAMS RIVER Surface: Bituminous Maintenance/Ownership: State

Tee Beam - 1929 Structure No. 200016004014012 Length: 28' Width: 30.5' Facility Carried: VT 00011 ML Bridge Type: TBEAM WIDE W/ STL BM Features Intersected: LYMAN BROOK Surface: Bituminous Maintenance/Ownership: State

Bridge <mark>41</mark>: Tee Beam - 1927 Structure No. 200016004114012 Length: 46' Width: 30.0' Facility Carried: VT 00011 ML Bridge Type: TBEAM WIDE W/ STL BM Features Intersected: MID. BR WILLIAMS RIVER Surface: Bituminous Maintenance/Ownership: State

