



DESCRIPTION BLOCK

Bridge <mark>10</mark>: Slab - 1933 Structure No. 300259001003171 Length: 14' Width: 30.0' Under Clearance: 5.0' Facility Carried: VT122 Bridge Type: CONCRETE SLAB Features Intersected: MILLERS RUN Surface: Bituminous Maintenance: State Bridge 11: Tee Beam - 1940 Structure No. 200259001103172 Length: 43' Width: 28.8' Facility Carried: VT 00122 ML Bridge Type: CONC TBM WID W STLBM Features Intersected: MILLER RUN Surface: Bituminous Maintenance/Ownership: State Stringer/multi-beam or girder - 1975 Structure No. 200259001203172 Length: 92' Width: 32.6' Facility Carried: VT 00122 ML Bridge Type: ROLLED BEAM Features Intersected: MILLER RUN Surface: Bituminous Maintenance/Ownership: State

Crash Locations 2010

2008