

Route Log and Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Section with questions or concerns.

DISTRICT TOWN ROUTE

4 WINDSOR Maj-0148



Maj-0148


ROUTE

Maj-0148

ETE mileage: 0.0 to 0.22

STRUCTURE DESCRIPTIONS

Bridge 33:
Girder and floorbeam system - 1930
Structure No. 200148003314232
Length: 52'
Height: 0.0'
Facility Carried: RAILROAD
Bridge Type: 2 RIVETED GIR F BEAM
Features Intersected: N.E.C.R.R. OVER TH NO 4



	Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet		Mileage by Town By Sheet				
Unknown	■ Bituminous Concrete Surface Treated	1 - Interstate 3 - Principal 5 - Major	(degrees) Left	← (ft)	(count)	0148 5 - Major Collector	0.220	WINDSOR - S01481423	0.22 of 0.22	DISTRICT	TOWN	Date: 11/1
Retreatment	■ Bituminous Macadam	2 - Other 4 - Minor 6 - Minor	Right							DISTRICT		Dutc. 11/1
Resurface	Cold Plane and	2 - Other 4 - Minor 6 - Minor Collector										
■ Bituminous I	Alix Bituminous Concrete Reclaimed Base and	Expressways	Grades	Traffic Counters	Crash Locations							1 of 1
Skinny Mix	Concrete Bituminous Concrete	Speed Zones	grade up	٩	Fatal Property Damage Only					1 4	WINDSOR	
Bituminous :	Seal Caravel	SPEED	(percent) grade down	(counter ID)	Injury Unknown Crash Type					4	WINDSOK	TWN milea
Indicated plans	available - http://ytransmap01 act state vt.us/rp/dpr/Dlwebstore/	25 30 35 40 45 50 55 60 65				Page Total	Mileage: 0.220 mi		Page Total Mileage: 0.22 mi			0.0 to 0.