## **Route Log and Progress Chart**


**DISTRICT DRAFT** Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.

**TOWN ROUTE** Maj-0233 UNDERHILL


8.35 of 8.35

Page Total Mileage: 8.35 mi

**DISTRICT** 



Maj-0233



STRUCTURE I	DESCRIPTIONS
dge 9: x beam or girders - multiple - 2001 ructure No. 200233000904152 ngth: 60' dth: 26.8' cility Carried: TR 01 FAS 233 dge Type: PS/PT CONC BOX BEAM atures Intersected: BROWNS RIVER rface: Bituminous sintenance/Ownership: Town	
dge 8: ringer/multi-beam or girder - 1957 ructure No. 200233000804152 ngth: 74' dth: 31.3' cility Carried: TR 01 FAS 233 dge Type: ROLLED BEAM atures Intersected: BROWNS RIVER rface: Bituminous sintenance/Ownership: Town	
dge 7: e Beam - 1927 ructure No. 200233000704152 ngth: 28' dth: 20.9' cility Carried: TR 01 FAS 233 dge Type: CONCRETE T-BEAM atures Intersected: SEYMOUR RIVER rface: Bituminous aintenance/Ownership: Town	
dge 6: ab - 1992 ructure No. 200233000604152 ngth: 24' dth: 28.0' cility Carried: TR 01 FAS 233 dge Type: CONCRETE SLAB atures Intersected: SEYMOUR BROOK rface: Bituminous sintenance/Ownership: Town	

**TOWN** 

UNDERHILL

**ROUTE** 

Maj-0233

ETE mileage:

0.43 to 8.78

Date: 11/10/16

1 of 1

TWN mileage:

0.0 to 8.35