

Route Log and Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Section with questions or concerns.

DISTRICT TOWN ROUTE

5 WAITSFIELD VT-17




Bridge 38: Stringer/multi-beam or girder - 1939 Structure No. 200200003812162

Length: 64'
Width: 25.4'
Facility Carried: VT 00017 ML
Bridge Type: ROLLED BEAM
Features Intersected: MILL BROOK

Maintenance/Ownership: State



STRUCTURE DESCRIPTIONS



			,								
Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet	Mileage by Town By Sheet	t]			
Unknown Retreatment Resurface Cold Plane and Surface Treated Gravel Plant Mix	1 - Interstate 3 - Principal 5 - Major Collector 2 - Other 4 - Minor 6 - Minor	(degrees) Left Right	← (ft) →	(count)	0200 5 - Major Collector	0.214 WAITSFIELD - V017-1216	0.214 of 0.214	DISTRICT	TOWN	Date: 11/14/16	ROUTE
Resurface Bituminous Mix Skinny Mix Concrete Cold Plane and Bituminous Concrete Reclaimed Base an Bituminous Concrete	d Expressways Speed Zones	Grades	Traffic Counters	Crash Locations Fatal Property Damage Only				5	WAITSFIELD	1 of 1 TWN mileage:	VT-17 ETE mileage:
Bituminous Seal Indicated plans available - http://vtransmap01.aot.state.vt.us/rp/dpr/Dlwebstore/	25 30 35 40 45 50 55 60 65	grade down	(322300 13)	Injury Unknown Crash Type	Page Total M	leage: 0.214 mi	Page Total Mileage: 0.214 mi			0.0 to 0.214	35.767 to 35.981