

Route Log and Progress Chart

DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.


DISTRICT TOWN ROUTE MOUNT HOLLY VT-155









STR	JCTURE D	ESCRIPTION	IS
Culvert 4: Culvert - 1964 Structure No. 30013300 Length: 10' Under Clearance: 4.0' Facility Carried: VT155 Bridge Type: RC BOX Features Intersected: BI Maintenance: State			
Culvert 6: Culvert - 1965 Structure No. 30013300 Length: 6' Under Clearance: 6.0' Facility Carried: VT155 Bridge Type: A.C.C.G.M Features Intersected: BI Maintenance: State	.P		
Culvert 7: Culvert - 1969 Structure No. 30013300 Length: 15' Under Clearance: 11.5' Facility Carried: VT155 Bridge Type: C.G.M.P.P. Features Intersected: M Maintenance: State	A.		
Culvert 9: Culvert - 1959 Structure No. 30013300 Length: 8' Under Clearance: 5.0' Facility Carried: VT155 Bridge Type: RC BOX Features Intersected: BI Maintenance: State			
Culvert 11: Culvert - 1919 Structure No. 30013300 Length: 16' Under Clearance: 9.0' Facility Carried: VT155 Bridge Type: MULTIPLA Features Intersected: M Maintenance: State	TE PIPE ARCH		
Bridge 12: Stringer/multi-beam or g Structure No. 20013300 Length: 41' Width: 30.8' Facility Carried: VT 001! Bridge Type: ROLLED E Features Intersected: M Surface: Bituminous Maintenance/Ownership	1211122 55 ML BEAM ILL RIVER		
Bridge 14: Girder and floorbeam sy Structure No. 20013300 Length: 162' Height: 0.0' Facility Carried: RAILRO Bridge Type: RIVETED Features Intersected: G	1411122 DAD TWO GIRDER	VT 155	








	Road Widths (ft)
p own	Traffic Counters
	is Duive. Montrollion VT. 0

dths →	AADT ← (count) →		
ounters	Crash Locations ■ Fatal □ Property Damage □ Injury □ Unknown Crash		

AADT		
(count)		0133
Fatal	Locations Property Damage Only Unknown Crash Type	_



	Mileage by Town By Sheet	
)3	MOUNT HOLLY - V155-1112	7.603 of 7.603
 mi		Page Total Mileage: 7.603 mi
nı		Page rotal Mileage: 7.603 mi