## Base Map 1 in = 0.4 milesStick Diagram Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps, +-+-++ Railroad Crossings Primary Structures Secondary Structures Divided State Highway

## **Route Log and Progress Chart**

Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.

**DRAFT** 

ETE - I089-0000S

Page Total Mileage: 9.000 mi

9.0 of 130.254


Page Total Mileage: 9.0 mi

**DISTRICT** 

**DISTRICT TOWN ROUTE** RICHMOND, WILLISTON, I-89 **BOLTON** 







■ Fatal □ Property Damage Only 89-2 1 - Interstate

■ Injury □ Unknown Crash Type

**High Crash Locations (HCL's)** 

1 - 100 301 - 400

101 - 200 401 - 800

**Traffic Counters** 

Stringer/multi-beam or girder - 1964 Structure No. 200089056S04112 Length: 222' Width: 30.0' Under Clearance: 19.0' Facility Carried: I 89 ML Structure Type: 3 SPAN ROLLED BEAM Features Intersected: I 89 OVER US 2 Surface: Bituminous Maintenance/Ownership: State

Bridge 57S: Stringer/multi-beam or girder - 1964 Structure No. 200089057S04112 Width: 42.0' Under Clearance: 24.5' Facility Carried: I 89 ML Structure Type: 4 SPAN ROLLED BEAM Features Intersected: I 89 OVER NECRR + BROOK Surface: Bituminous Maintenance/Ownership: State

Girder and floorbeam system - 1962 Structure No. 200089058S04112 Length: 558' Width: 30.0' Under Clearance: 35.0' Facility Carried: I 89 ML Structure Type: 3 SP CONT (2) GIRDER Features Intersected: I 89 OVER WIN. RIV.+TH16 Surface: Bituminous Maintenance/Ownership: State

Stringer/multi-beam or girder - 1962 Structure No. 200089059S04112 Length: 152' Width: 30.0' Under Clearance: 15.17' Facility Carried: I 89 ML Structure Type: 3 SPAN ROLLED BEAM Features Intersected: I 89 OVER TH NO 8 Surface: Bituminous Maintenance/Ownership: State

Bridge 59-1: Structure No. 30008959-104111 Length: 14' Under Clearance: 12.0' Facility Carried: 189 Structure Type: RC BOX Features Intersected: LAND ACCESS ROAD Maintenance: State

Structure No. 30008959-204111 Structure Type: CGMPP - lined Features Intersected: BROOK Maintenance/Ownership: State

72.0 to 81.0

**TOWN** 

RICHMOND, WILLISTON,

**BOLTON** 

(percent) grade up

1 - Interstate 3 - Principal Arterial

Freeways and

Expressways

4 - Minor Arterial

Speed Zones

Bituminous Concrete
Bituminous Macadam

Surface Treated
Gravel

Cold Plane and
Bituminous Concrete
Concrete
Concrete
Concrete

Unknown

Resurface

■ Bituminous Mix

Skinny Mix Concrete

Retreatment Bituminous Macadam