



DISTRICT	TOWN	ROUTE
5	UNDERHILL	Maj-0233



Maj-0233



STRUCTURE DESCRIPTIONS

Bridge 9:
Box beam or girders - multiple - 2001
Structure No. 200233000904152
Length: 60'
Height: 5.33'
Width: 2.7'
Facility Carried: TR 01 FAS 233
Structure Type: PS/PT CONG BOX BEAM
Features Intersected: BROWNS RIVER
Surface: Bituminous
Maintenance/Ownership: Town

Bridge 8:
Stringer/multi-beam or girder - 1957
Structure No. 200233000804152
Length: 74'
Height: 5.33'
Width: 3.1'
Facility Carried: TR 01 FAS 233
Structure Type: ROLLED BEAM
Features Intersected: BROWNS RIVER
Surface: Bituminous
Maintenance/Ownership: Town

Bridge 7:
Tee Beam - 1927
Structure No. 200233000704152
Length: 28'
Height: 5.33'
Width: 2.1'
Facility Carried: TR 01 FAS 233
Structure Type: CONCRETE T-BEAM
Features Intersected: SEYMOUR RIVER
Surface: Bituminous
Maintenance/Ownership: Town

Bridge 6:
Slab - 1992
Structure No. 200233000604152
Length: 24'
Height: 5.33'
Width: 2.8'
Facility Carried: TR 01 FAS 233
Structure Type: CONCRETE SLAB
Features Intersected: SEYMOUR BROOK
Surface: Bituminous
Maintenance/Ownership: Town

Road Widths	Travellane	18
Roadway		20
Lane Count		2
Base		
Subbase		
Curves		4
Grades		
Guardrails		
Rumblestrips		
Historic Projects	Timeline showing project years from 1978 to 2021, including 1990 TH 2408, 1986 Unknown, 2002 BRS 0233(2), 1987 Unknown, 1988 Unknown, 1989 Unknown, 1992 Unknown, 1993 Unknown, 1994 Unknown, 1995 Unknown, 1996 Unknown, 1997 Unknown, 1998 Unknown, 1999 Unknown, 2000 Unknown, 2001 Unknown, 2002 BRS 0233(2), 2003 Unknown, 2004 Unknown, 2005 Unknown, 2006 Unknown, 2007 Unknown, 2008 Unknown, 2009 Unknown, 2010 Unknown, 2011 Unknown, 2012 Unknown, 2013 Unknown, 2014 Unknown, 2015 Unknown, 2016 Unknown, 2017 Unknown, 2018 Unknown, 2019 Unknown, 2020 Unknown, 2021 Unknown.	
Maintenance Garage		
Speed Zone		
Functional Class		5
National Highway System		
Limited Access Highway		
Customer Service Level		
Traffic Counters	UHRL04, UHRL14, UHRL09, UHRL39, UHRL40	
AADT	2021: 237, 2797; 2020: 2469; 2019: 2915; 2018: 3200; 2017: 3200	1003, 931, 1099, 1000, 1000
Crash Locations	Timeline showing crash locations from 2018 to 2022.	

<p>Historic Projects</p> <ul style="list-style-type: none"> Unknown Bituminous Concrete Retreatment Resurface Bituminous Mix Skippy Mix Bituminous Seal 	<p>Functional Class</p> <ul style="list-style-type: none"> 1 - Interstate System 2 - Other 3 - Principal Arterial 4 - Minor Arterial 5 - Major Collector 6 - Minor Collector 	<p>Curves</p> <ul style="list-style-type: none"> Left Right 	<p>Grades</p> <ul style="list-style-type: none"> Up Down 	<p>Traffic Counters</p> <ul style="list-style-type: none"> Continuous (CTC) Weight-In-Motion (WIM) Short-Term, Scheduled Short-Term, Unscheduled 	<p>Crash Locations</p> <ul style="list-style-type: none"> Fatal Injury Property Damage Only Unknown Crash Type 	<p>Mileage by Functional Class By Sheet</p> <p>0233 5 - Major collector 8.350</p>	<p>Mileage by Town By Sheet</p> <p>UNDERHILL - S02330415 8.35 of 8.35</p>	<p>DISTRICT</p> <p>5</p>	<p>TOWN</p> <p>UNDERHILL</p>	<p>Date: 10/02/22</p>	<p>ROUTE</p> <p>Maj-0233</p>	<p>ETE mileage:</p> <p>0.43 to 8.78</p>
---	---	--	---	---	---	--	--	---------------------------------	-------------------------------------	------------------------------	-------------------------------------	--