## **Route Log and Progress Chart**

**DRAFT** Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.

DERBY - U005-1007S


Page Total Mileage: 0.440 mi

0.44 of 0.44


Page Total Mileage: 0.44 mi

**DISTRICT** 

DISTRICT	TOWN	ROUTE
9	DERBY	US-5







■ Fatal □ Property Damage Only 034-3 4 - Minor Arterial

Continuous (CTC)

▲ Short-Term, Scheduled

△ Short-Term, Unscheduled

High Crash Locations (HCL's)

HCL No. 201 - 300 (21 - 30)

1 - 100 (1 - 10) 301 - 400 (31 - 40)

Sections (& Intersections)

Left (degrees) Right grade up

## STRUCTURE DESCRIPTIONS

Stringer/multi-beam or girder - 1970 Structure No. 200034017810072 Length: 331' Width: 64.3' Under Clearance: 17.33' Facility Carried: US 05 Structure Type: 4 SP CONT ROLLED BM Features Intersected: I 91 UNDER US 5 Surface: Bituminous Inspection Date: 52/24 Maintenance/Ownership: State

1 - Interstate
System
2 - Other
Freeways and
System
4 - Minor
Arterial

Unknown
Retreatment
Resurface
Bituminous Macadam
Cold Plane and
Bituminous Concrete
Bituminous Concrete
Bituminous Concrete
Bituminous Concrete
Cold Plane and
Bituminous Concrete
Bituminous Concrete

Skinny Mix Concrete