



REVISIONS & CORRECTIONS
 Slotted holes in beam web at piers deleted. Pile splice changed. 8-26-60

DRAWN BY I.M. BARN 2-56
 TRACED BY A.P. McPHERSON 2-56
 CHECKED BY L.L. HUBBARD 2-56

CORRECT 13 July 1960
 Approved 17 July 1960
 CHIEF ENGINEER

CONSTRUCTION DETAILS FOR I-BEAM BRIDGES