



\* THREE CABLE GUARD RAIL WITH LIGHT STEEL POSTS, ITEM 233  
 N.D. 1931°00' - 1936°16' H  
 N.D. 1902°18' - 1938°30' H  
 S.D. 1931°00' - 1938°16' H  
 S.B. 1932°40' - 1934°00' R

DRILLING AND BLASTING OF SOLID ROCK SUGGRADE ITEM 115  
 S.D. 1937°00' - 1937°00'  
 N.D. 1937°00' - 1937°00'  
 DRILLING AND BLASTING OF SOLID ROCK ITEM 114  
 S.D. 1936°00' - 1936°50'

PROPERTY LINE FENCE MOD ITEM 523-11  
 S.D. 1931°00' - 1936°20' H  
 S.D. 1937°50' - 1937°00' H  
 N.B. 1931°00' - 1937°00' H  
 N.B. 1937°50' - 1937°00' H

Blank Guardrail N.B. 1936°30' R  
 Bridge Piling Over Approaches N.B. 1937°10' - 1937°10' H  
 N.B. 1937°10' - 1937°10' H  
 N.B. 1937°10' - 1937°10' H  
 N.B. 1937°10' - 1937°10' H  
 N.B. 1937°10' - 1937°10' H

BROOKFIELD  
 IM 089-1(59)  
 SHEET 16  
 FOR REFERENCE ONLY

RANDOLPH-BROOKFIELD  
 SURVEYED BY: Fall DATE: 7-64  
 DRAWN BY: Boston DATE: 7-64  
 TRACED BY: S.C.G. DATE: 7-68  
 (28)  
 PROJ. I NO. 89-1  
 SHEET 16 OF 68 SHEETS

Control of Access is complete on this Sheet.