



97+00	1307.00
97+10	1307.50
97+20	1308.00
97+30	1308.50
97+40	1309.00
97+50	1309.50
97+60	1310.00
97+70	1310.50
97+80	1311.00
97+90	1311.50
98+00	1312.00
98+10	1312.50
98+20	1313.00
98+30	1313.50
98+40	1314.00
98+50	1314.50
98+60	1315.00
98+70	1315.50
98+80	1316.00
98+90	1316.50
99+00	1317.00
99+10	1317.50
99+20	1318.00
99+30	1318.50
99+40	1319.00
99+50	1319.50
99+60	1320.00
99+70	1320.50
99+80	1321.00
99+90	1321.50
100+00	1322.00
100+10	1322.50
100+20	1323.00
100+30	1323.50
100+40	1324.00
100+50	1324.03

SHEET 6

5