



CURVE #10
 Δ 6°30' LT
 R 5°
 D 1146.3
 L 65.1
 T 130.0
 E 1.8

Surface treatment of intersection and any extra work done outside of limits of pavement is to be paid for by the village of Hardwick. Grade of intersection may be varied by the engineer to meet conditions in the field.

