







A.D. WOOD  
 F.W. HAMMERS  
 3/19/33

A.D. WOOD  
 F.W. HAMMERS  
 3/19/33





624	595.1 592.65	625	594.8 592.25	594.8 592.25	595.2 592.64	596.6 594.0	597.2 594.6	598.2 595.66	599.4 596.82	600.7 604.41	603.9 603.44	605.0 604.07	607.0 604.41	610.5 610.48	613.2 613.71	615.0 615.0	616.5 616.58	617.0 617.71	617.7 618.35	619.0 619.36	619.9 619.92	620.6 620.6	621.1 621.58	621.4 621.75	621.6 621.94	621.8 622.13
-----	-----------------	-----	-----------------	-----------------	-----------------	----------------	----------------	-----------------	-----------------	-----------------	-----------------	-----------------	-----------------	-----------------	-----------------	----------------	-----------------	-----------------	-----------------	-----------------	-----------------	----------------	-----------------	-----------------	-----------------	-----------------

BM #63 Spike in Root of 2 1/2" Maple 16' Lt. Sta. 635+35 Elev 622.27

PUTNAM - WOOD 1933  
 F.W. HAYWARD 3/1933

A.D. WOOD 3/1933  
 F.W. HAYWARD 3/1933

FIELD NO. DIST. NO. STATE SHEET NO. SHEETS  
 NCS 174 1933 6 21





B.M. # 64 Spot on Conc Fdn. Gas Pump 15' Lt. Sta. 645+38 Elev 629.22

SERIES NRS NO. 149A  
 SHEET 6 OF 21

AD. Moore  
 FARMINGTON, UTAH  
 1933



AD. Moore  
 FARMINGTON, UTAH  
 1933



B.M. # 65 Spike in Foot of 12" Twin Elm 25' Rt. Sta 660+25 Elev. 628.09

A.D. WOOD CIVIL ENGINEER

A.D. WOOD CIVIL ENGINEER



BM #66 Spike in Root of 24' Elm 30' Lt Sta. 669+25 Elev. 628.60

6