

WOOD GUARD RAIL REQUIRED

Station	Length
Sta 824100 - 824150	50 FT
Sta 824150 - 824200	50 FT
Sta 824200 - 824250	50 FT
Sta 824250 - 824300	50 FT
Sta 824300 - 824350	50 FT
Sta 824350 - 824400	50 FT
Sta 824400 - 824450	50 FT

CABLE GUARD RAIL REQUIRED

Station	Length
Sta 824100 - 824150	50 FT
Sta 824150 - 824200	50 FT
Sta 824200 - 824250	50 FT
Sta 824250 - 824300	50 FT
Sta 824300 - 824350	50 FT
Sta 824350 - 824400	50 FT
Sta 824400 - 824450	50 FT

NEW CULVERTS REQUIRED

Sta 824100 - 18" Reinforced Concrete Pipe Culvert
 Concrete Class A (1-2-4)
 Reinforcing Steel
 Length 32 ft

Sta 824350 - 18" Reinforced Concrete Pipe Culvert
 Concrete Class A (1-2-4)
 Reinforcing Steel
 Length 32 ft

W.E. MUNNET

CULVERT REPAIRS REQUIRED

Sta 824170 - 48" Stone Box Culvert
 Repair - New floor - 2" thick
 Concrete Class A (1-2-4)
 Reinforcing Steel
 Length 7.9 ft

