

GUARD RAIL REQUIRED

ON LEFT

Sta 410+88 to Sta 411+12	Length 24 ft	
411+12	413+32	24'
413+32	415+52	24'
415+52	417+72	24'
417+72	419+92	24'
419+92	421+12	24'
421+12	423+32	24'
423+32	425+52	24'
425+52	427+72	24'
427+72	429+92	24'
429+92	431+12	24'
431+12	433+32	24'
433+32	435+52	24'
435+52	437+72	24'
437+72	439+92	24'
439+92	441+12	24'
441+12	443+32	24'
443+32	445+52	24'
445+52	447+72	24'
447+72	449+92	24'
449+92	451+12	24'
451+12	453+32	24'
453+32	455+52	24'
455+52	457+72	24'
457+72	459+92	24'
459+92	461+12	24'
461+12	463+32	24'
463+32	465+52	24'
465+52	467+72	24'
467+72	469+92	24'
469+92	471+12	24'
471+12	473+32	24'
473+32	475+52	24'
475+52	477+72	24'
477+72	479+92	24'
479+92	481+12	24'
481+12	483+32	24'
483+32	485+52	24'
485+52	487+72	24'
487+72	489+92	24'
489+92	491+12	24'
491+12	493+32	24'
493+32	495+52	24'
495+52	497+72	24'
497+72	499+92	24'
499+92	501+12	24'
501+12	503+32	24'
503+32	505+52	24'
505+52	507+72	24'
507+72	509+92	24'
509+92	511+12	24'
511+12	513+32	24'
513+32	515+52	24'
515+52	517+72	24'
517+72	519+92	24'
519+92	521+12	24'
521+12	523+32	24'
523+32	525+52	24'
525+52	527+72	24'
527+72	529+92	24'
529+92	531+12	24'
531+12	533+32	24'
533+32	535+52	24'
535+52	537+72	24'
537+72	539+92	24'
539+92	541+12	24'
541+12	543+32	24'
543+32	545+52	24'
545+52	547+72	24'
547+72	549+92	24'
549+92	551+12	24'
551+12	553+32	24'
553+32	555+52	24'
555+52	557+72	24'
557+72	559+92	24'
559+92	561+12	24'
561+12	563+32	24'
563+32	565+52	24'
565+52	567+72	24'
567+72	569+92	24'
569+92	571+12	24'
571+12	573+32	24'
573+32	575+52	24'
575+52	577+72	24'
577+72	579+92	24'
579+92	581+12	24'
581+12	583+32	24'
583+32	585+52	24'
585+52	587+72	24'
587+72	589+92	24'
589+92	591+12	24'
591+12	593+32	24'
593+32	595+52	24'
595+52	597+72	24'
597+72	599+92	24'
599+92	601+12	24'
601+12	603+32	24'
603+32	605+52	24'
605+52	607+72	24'
607+72	609+92	24'
609+92	611+12	24'
611+12	613+32	24'
613+32	615+52	24'
615+52	617+72	24'
617+72	619+92	24'
619+92	621+12	24'
621+12	623+32	24'
623+32	625+52	24'
625+52	627+72	24'
627+72	629+92	24'
629+92	631+12	24'
631+12	633+32	24'
633+32	635+52	24'
635+52	637+72	24'
637+72	639+92	24'
639+92	641+12	24'
641+12	643+32	24'
643+32	645+52	24'
645+52	647+72	24'
647+72	649+92	24'
649+92	651+12	24'
651+12	653+32	24'
653+32	655+52	24'
655+52	657+72	24'
657+72	659+92	24'
659+92	661+12	24'
661+12	663+32	24'
663+32	665+52	24'
665+52	667+72	24'
667+72	669+92	24'
669+92	671+12	24'
671+12	673+32	24'
673+32	675+52	24'
675+52	677+72	24'
677+72	679+92	24'
679+92	681+12	24'
681+12	683+32	24'
683+32	685+52	24'
685+52	687+72	24'
687+72	689+92	24'
689+92	691+12	24'
691+12	693+32	24'
693+32	695+52	24'
695+52	697+72	24'
697+72	699+92	24'
699+92	701+12	24'
701+12	703+32	24'
703+32	705+52	24'
705+52	707+72	24'
707+72	709+92	24'
709+92	711+12	24'
711+12	713+32	24'
713+32	715+52	24'
715+52	717+72	24'
717+72	719+92	24'
719+92	721+12	24'
721+12	723+32	24'
723+32	725+52	24'
725+52	727+72	24'
727+72	729+92	24'
729+92	731+12	24'
731+12	733+32	24'
733+32	735+52	24'
735+52	737+72	24'
737+72	739+92	24'
739+92	741+12	24'
741+12	743+32	24'
743+32	745+52	24'
745+52	747+72	24'
747+72	749+92	24'
749+92	751+12	24'
751+12	753+32	24'
753+32	755+52	24'
755+52	757+72	24'
757+72	759+92	24'
759+92	761+12	24'
761+12	763+32	24'
763+32	765+52	24'
765+52	767+72	24'
767+72	769+92	24'
769+92	771+12	24'
771+12	773+32	24'
773+32	775+52	24'
775+52	777+72	24'
777+72	779+92	24'
779+92	781+12	24'
781+12	783+32	24'
783+32	785+52	24'
785+52	787+72	24'
787+72	789+92	24'
789+92	791+12	24'
791+12	793+32	24'
793+32	795+52	24'
795+52	797+72	24'
797+72	799+92	24'
799+92	801+12	24'
801+12	803+32	24'
803+32	805+52	24'
805+52	807+72	24'
807+72	809+92	24'
809+92	811+12	24'
811+12	813+32	24'
813+32	815+52	24'
815+52	817+72	24'
817+72	819+92	24'
819+92	821+12	24'
821+12	823+32	24'
823+32	825+52	24'
825+52	827+72	24'
827+72	829+92	24'
829+92	831+12	24'
831+12	833+32	24'
833+32	835+52	24'
835+52	837+72	24'
837+72	839+92	24'
839+92	841+12	24'
841+12	843+32	24'
843+32	845+52	24'
845+52	847+72	24'
847+72	849+92	24'
849+92	851+12	24'
851+12	853+32	24'
853+32	855+52	24'
855+52	857+72	24'
857+72	859+92	24'
859+92	861+12	24'
861+12	863+32	24'
863+32	865+52	24'
865+52	867+72	24'
867+72	869+92	24'
869+92	871+12	24'
871+12	873+32	24'
873+32	875+52	24'
875+52	877+72	24'
877+72	879+92	24'
879+92	881+12	24'
881+12	883+32	24'
883+32	885+52	24'
885+52	887+72	24'
887+72	889+92	24'
889+92	891+12	24'
891+12	893+32	24'
893+32	895+52	24'
895+52	897+72	24'
897+72	899+92	24'
899+92	901+12	24'
901+12	903+32	24'
903+32	905+52	24'
905+52	907+72	24'
907+72	909+92	24'
909+92	911+12	24'
911+12	913+32	24'
913+32	915+52	24'
915+52	917+72	24'
917+72	919+92	24'
919+92	921+12	24'
921+12	923+32	24'
923+32	925+52	24'
925+52	927+72	24'
927+72	929+92	24'
929+92	931+12	24'
931+12	933+32	24'
933+32	935+52	24'
935+52	937+72	24'
937+72	939+92	24'
939+92	941+12	24'
941+12	943+32	24'
943+32	945+52	24'
945+52	947+72	24'
947+72	949+92	24'
949+92	951+12	24'
951+12	953+32	24'
953+32	955+52	24'
955+52	957+72	24'
957+72	959+92	24'
959+92	961+12	24'
961+12	963+32	24'
963+32	965+52	24'
965+52	967+72	24'
967+72	969+92	24'
969+92	971+12	24'
971+12	973+32	24'
973+32	975+52	24'
975+52	977+72	24'
977+72	979+92	24'
979+92	981+12	24'
981+12	983+32	24'
983+32	985+52	24'
985+52	987+72	24'
987+72	989+92	24'
989+92	991+12	24'
991+12	993+32	24'
993+32	995+52	24'
995+52	997+72	24'
997+72	999+92	24'
999+92	1001+12	24'

ON RIGHT

410+88	411+12	24'
412+36	412+60	24'
413+65	413+89	24'
415+10	415+34	24'
416+33	416+57	24'

TOTAL THIS SHEET 400 ft.

CULVERT REPAIRS REQUIRED


Sta 411+03
1-3-6 Concrete Headwalls 20 cu yds.

Sta 412+68 2x8 Concrete 28.5 ft.
1-3-4 Concrete 5.8 cu yds.
1-3-6 " 26 "


Sta 418+77
1-3-6 Concrete Headwalls 25 cu yds.

FED. ROAD DIST. NO.	STATE	FED. AID PROJ. NO.	FISCAL YEAR	SHEET NO.	TOTAL SHEETS
3	Vt.	12	FY 1958	29	132

L.L. Davis
L.C.B. and Chas. W. W. Jr.



L.L. Davis
L.C.B. and Chas. W. W. Jr.



BM Spike in corner of barn right of curve, Elev 688.8
BM High point of road under drive to barn right of curve, Elev 715.7

Series 100-100-100