



NOTES:  
Foundation information obtained for design purposes only, and the State assumes no responsibility whatsoever for the sufficiency or accuracy of the information shown. Boulders may be encountered at any pier or abutment location. For location of borings, see Sheet 1.

BRIDGE 40  
FOR REFERENCE ONLY  
SHEET 7 OF 16

VERMONT  
STATE HIGHWAY DEPARTMENT  
TOWN OF BRIDGEWATER  
U.S. ROUTE 4

BRIDGE AT STA. 223+605  
BORING LOGS, FRAMING PLAN  
& TYPICAL BRIDGE SECTION

WM. H. McFARLAND  
ENGINEER  
BINGHAMTON, N.Y.

DESIGNED: E.W.C. CHECKED: T.L.S. DATE: Feb. 6, 1957  
DRAWN: E.F.D. IN CHARGE: H.C.C. SCALE: AS SHOWN

PROJECT NO. Q-020-2(5) SH. 41 OF 141

NOTE:  
1. - For General Notes, see sheet #1.