



540 Commercial Street - Manchester, NH 03101
(603) 668-8223 • Fax: (603) 668-8302
eld@eldengineers.com • www.eldengineers.com
New Hampshire • Vermont • Maine

TO: Martha Evans-Mongeon

FROM: John Byatt

DATE: June 2, 2005

RE: Attachment to review truss steel shop drawings
Jamaica
BRF 013-1(8)
CLD Reference No. 90-0284

A review of the truss shop drawing submittal has been completed. The drawings are stamped "Provide as Corrected"; however, the details of the top strut connection to the top chord (sheets 130B and 131B) must be resubmitted to eliminate the bent angles as currently shown.

At the conclusion of the prefabrication meeting it was our understanding that the fabricator would submit plans, for approval, indicating the connections that would be exempt from the 0.5 slip coefficient criteria. The fabricator no longer intends to make this submission, and therefore all the truss connections must meet the 0.5 slip coefficient requirement.

*my copy
to keep. Martha*