



ONE - BOTTOM CHORD - 4BC2E (CONTINUED)
(L2-L2' EAST)

SHOP NOTE:
ALL STEEL FOR BOTTOM CHORD
ASSEMBLY SHALL BE GALVANIZED

Vermont Agency of Transportation
RECEIVED
CK'D BY TCF OK'D BY SSS
7:43 am, Apr 12, 2011
RESUBMIT APPROVED X
BY KMH DATE 4-12-11

WORK THIS DWG. WITH DWG. 4AC & 4C.

03/23/11	REVISED AS PER APPROVAL COMMENTS	JM	PWR			
03/01/11	REVISED AS PER APPROVAL COMMENTS	JM	PWR			
0						
REV.	DATE	REMARKS	DWN	CHK	APVL	SHOP
MATERIAL:		SURFACE PREP. & PAINT:	HOLES:		SHOP BOLTS:	
M270-50 (U.N.)		SEE DWG GN1	1/8" (U.N.)		AS NOTED	
DESCRIPTION: BOTTOM CHORD 4BC2E						
CASCO BAY STEEL STRUCTURES, INC.						
75 SPRING HILL ROAD			SACO, MAINE 04072			
PHONE (207) 282-7360			FAX. (207) 282-1179			
STRUCTURE: Vermont Route 100A					DRAWN:	DATE:
Bridge No. 14					RB	9/27/10
Bridgewater					CHKD:	DATE:
County of Windsor					WJL	10/18/10
LOCATION: BRIDGEWATER, VERMONT				JOB NO.	DWG NO.	
PROJ NO. BRS 0148(4)				454	4BC	
CUSTOMER: VT AOT				REV.	A	