



Vermont Agency of Transportation
RECEIVED
 CK'D BY TCF OK'D BY SSS
 7:43 am, Apr 12, 2011
 RESUBMIT APPROVED X
 BY KMH DATE 4-12-11

ONE - TOP CHORD - 5TC1W
(U1-U3 WEST)

ONE - TOP CHORD - 5TC3E
(U1'-U3' EAST)

ALIKE EXCEPT FOR MARK

SHOP NOTE:
 ALL STEEL FOR TOP CHORD ASSEMBLIES SHALL BE GALVANIZED

- NOTES:**
1. FOR GENERAL NOTES SEE DWG. GN1.
 2. FOR STANDARD DETAILS SEE DWG. X1 & X2.
 3. "NF" - DENOTES NEAR FACE OF ASS'Y.
 4. "FF" - DENOTES FAR FACE OF ASS'Y.
 5. "BF" - DENOTES BOTH FACES OF ASSEMBLY.
 6. ALL BOLTS SHALL BE FULLY TORQUED (UN).
 7. BTS - DENOTES BOLT TO SHIP OR SECURE FOR SHIPMENT.
 8. HDS - DENOTES BOLT HEADS.

MATERIAL: M270-50 (U.N.)	SURFACE PREP. & PAINT: SEE DWG GN1	HOLES: 1/8" Ø (U.N.)	SHOP BOLTS: AS NOTED
DESCRIPTION: TOP CHORD 5TC1W & 5TC3E			
CASCO BAY STEEL STRUCTURES, INC.			
75 SPRING HILL ROAD PHONE (207) 282-7360		SACO, MAINE 04072 FAX. (207) 282-1179	
STRUCTURE: Vermont Route 100A Bridge No. 14 Bridgewater County of Windsor	DRAWN: RB	DATE: 9/28/10	
	CHKD: WJL	DATE: 10/18/10	
LOCATION: BRIDGEWATER, VERMONT	JOB NO. 454	DWG NO. 5AB	
PROJ NO. BRS 0149(4)	CUSTOMER: VT AOT	REV.:	

REV.	DATE	REMARKS	DWN	CHK	APVL	SHOP
03/23/11		REVISED AS NOTED	JM	PWR		
03/01/11		REVISED AS PER APPROVAL COMMENTS	JM	PWR		
0						