

UPDATE

Filled Out By: G. Demers

Date/Time: 10/28/10 1120

**Culvert Inspection Form**

Railroad: <u>WACR CRL</u>	Town: <u>TWETFORD</u>
Valuation Sheet: <u>V 43</u> <u>18</u>	Valuation Stationing: <u>941 + 33</u>
Mile Post: <u>D 23.15</u>	GPS Coordinates: N: <u>43 51 46</u> W: <u>72 11 10</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

INLET (WEST) 6' X 4' CONCRETE BOX W/ WINGWALLS

OUTLET (EAST) 3 X 4' STONE BOX (DOUBLE)

Height from Rail: 20'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 140,85

Number of Photos Taken: 3

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
THERE IS A D.I. ON THIS CULVERT BETWEEN  
US ROUTE 5 AND THE ROW  
\_\_\_\_\_  
\_\_\_\_\_

140  
—  
85







