



culvert should be flushed.









Extensive corrosion and scattered perforations throughout.









