



















Culvert will need replacing in the near future.









Undermined at outlet. 2 to 3 feet under toe.





