

NIC Program Steps

-----

Step	Program	Step Begins	Pattern	Override
1	1	0600	2	NO
2	1	0900	1	NO
3	1	1500	3	NO
4	1	1800	1	NO
5	2	0000	1	NO
6	1	2000	0	YES