

TOD Program Steps

 Step 3 Program 1 Step Begins 1430

Flash. Dimming Enable.
 Red Rest Alt Veh Extension
 Spare 5. Det Log Enable.
 Spare 3. Spare 4
 Type 0 Dly Enable. . . Spare 2
 Det Diag Plan. . . . 0

| | Phase Number | | | | | | | | | | | |
|-------------------------------|--------------|---|---|---|---|---|---|---|---|----|----|----|
| | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Max 2 Enable | . | . | . | . | . | . | . | . | . | . | . | . |
| Max 3 Enable | X | X | X | X | X | X | X | X | X | . | . | . |
| Veh Recall | . | . | . | . | . | . | . | . | . | . | . | . |
| Veh Max Recall | . | X | . | . | . | X | . | . | . | . | . | . |
| Ped Recall | . | . | . | . | . | . | . | . | . | . | . | . |
| Cond Service Inhibit. | . | . | . | . | . | . | . | . | . | . | . | . |
| Phase Omit | . | . | . | . | . | . | . | . | . | . | . | . |
| Special Function | . | . | . | . | . | . | . | . | . | . | . | . |

Alt Sequence A B C D E F

Step 4 Program 1 Step Begins 1900

Flash. Dimming Enable.
 Red Rest Alt Veh Extension
 Spare 5. Det Log Enable.
 Spare 3. Spare 4
 Type 0 Dly Enable. . . Spare 2
 Det Diag Plan. . . . 0

| | Phase Number | | | | | | | | | | | |
|-------------------------------|--------------|---|---|---|---|---|---|---|---|----|----|----|
| | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Max 2 Enable | X | X | X | X | X | X | X | X | X | . | . | . |
| Max 3 Enable | . | . | . | . | . | . | . | . | . | . | . | . |
| Veh Recall | . | X | . | . | . | X | . | . | . | . | . | . |
| Veh Max Recall | . | . | . | . | . | . | . | . | . | . | . | . |
| Ped Recall | . | . | . | . | . | . | . | . | . | . | . | . |
| Cond Service Inhibit. | . | . | . | . | . | . | . | . | . | . | . | . |
| Phase Omit | . | . | . | . | . | . | . | . | . | . | . | . |
| Special Function | . | . | . | . | . | . | . | . | . | . | . | . |

Alt Sequence A B C D E F
