

NIC Program Steps

---

Step	Program	Step Begins	Pattern	Override
1	1	0600	1	NO
2	1	1500	2	NO
3	1	1800	1	NO
4	1	1900	3	NO
5	1	2200	0	NO
7	2	0600	1	NO
8	2	0000	0	NO