

TOD Program Steps

-----

Step 7            Program 2            Step Begins    0000

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Flash. . . . .             | X | Dimming Enable. . . . .     |
| Red Rest . . . . .         | . | Alt Veh Extension . . . . . |
| Spare 5. . . . .           | . | Det Log Enable. . . . .     |
| Spare 3. . . . .           | . | Spare 4 . . . . .           |
| Type 0 Dly Enable. . . . . | . | Spare 2 . . . . .           |
| Det Diag Plan. . . . .     | 0 |                             |

|                               | Phase Number |   |   |   |   |   |   |   |   |    |    |    |
|-------------------------------|--------------|---|---|---|---|---|---|---|---|----|----|----|
|                               | 1            | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Max 2 Enable . . . . .        | .            | . | . | . | . | . | . | . | . | .  | .  | .  |
| Max 3 Enable . . . . .        | .            | . | . | . | . | . | . | . | . | .  | .  | .  |
| Veh Recall . . . . .          | .            | . | . | . | . | . | . | . | . | .  | .  | .  |
| Veh Max Recall . . . . .      | .            | . | . | . | . | . | . | . | . | .  | .  | .  |
| Ped Recall . . . . .          | .            | . | . | . | . | . | . | . | . | .  | .  | .  |
| Cond Service Inhibit. . . . . | .            | . | . | . | . | . | . | . | . | .  | .  | .  |
| Phase Omit . . . . .          | .            | . | . | . | . | . | . | . | . | .  | .  | .  |
| Special Function . . . . .    | .            | . | . | . | . | . | . | . | . | .  | .  | .  |

|                        |   |   |   |   |   |   |
|------------------------|---|---|---|---|---|---|
| Alt Sequence . . . . . | A | B | C | D | E | F |
|------------------------|---|---|---|---|---|---|

-----