

TOD Program Steps

Step 1 Program 1 Step Begins 0600

Flash.
Red Rest
Spare 5.
Spare 3.
Type 0 Dly Enable. . .
Det Diag Plan. . . . 0

Phase Number
1 2 3 4 5 6 7 8 9 10 11 12

Max 2 Enable
Max 3 Enable
Veh Recall
Veh Max Recall
Ped Recall
Cond Service Inhibit.
Phase Omit
Special Function

A B C D E F

Alt Sequence

Step 2 Program 1 Step Begins 2200

Flash. X
Red Rest
Spare 5.
Spare 3.
Type 0 Dly Enable. . .
Det Diag Plan. . . . 0

Phase Number
1 2 3 4 5 6 7 8 9 10 11 12

Max 2 Enable
Max 3 Enable
Veh Recall
Veh Max Recall
Ped Recall
Cond Service Inhibit.
Phase Omit
Special Function

A B C D E F

Alt Sequence
