




Route Log and Progress Chart

DRAFT

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Section with questions or concerns.

DISTRICT	TOWN	ROUTE
3	RUTLAND TOWN	BUS-4




Road Widths	Travellane: 48	Roadway: 68	Lane Count: 4	Base: 4'	Subbase: 18' Gravel
--------------------	----------------	-------------	---------------	----------	---------------------

Curves	3	6
---------------	---	---

Grades	
---------------	--

Guardrails	
-------------------	--

Rumblestrips	
---------------------	--



Maintenance Garage	District 3 - DMF Maintenance Castleton Garage
---------------------------	---

Speed Zone	
-------------------	--

Functional Class	3
-------------------------	---

National Highway System	
--------------------------------	--

Limited Access Highway	
-------------------------------	--

Customer Service Level	Arterial Highway
-------------------------------	------------------

Traffic Counters	31120605-W 31120605-E
-------------------------	-----------------------

AADT	2022: 10562, 11135, 11198	2021: 10468, 11036, 11658	2020: 9338, 9845, 10398	2019: 11346, 11962, 12634	2018: 13000, 13500
-------------	---------------------------	---------------------------	-------------------------	---------------------------	--------------------

Crash Locations	(Incomplete) 2023	2022	2021	2020	2019
------------------------	-------------------	------	------	------	------

STRUCTURE DESCRIPTIONS	
Bridge B4-3:	Stringer/multi-beam or girder - 1959 Structure No: 203200B4-311202 Length: 116' Height: 100.0' Width: 56.0' Weight Limit: 0 Facility Carried: US 00BR4 BUS. Structure Type: WELDED PLATE GIRDER Features Intersected: CLARENDON RIVER Surface: Bituminous Inspection Date: 5/2021 Maintenance/Ownership: State
Bridge B4-4:	Stringer/multi-beam or girder - 1959 Structure No: 203200B4-411202 Length: 147' Height: 100.0' Width: 67.0' Weight Limit: 0 Facility Carried: US 00BR4 BUS. Structure Type: 2 SPAN ROLLED BEAM Features Intersected: OTTER CREEK Surface: Bituminous Inspection Date: 5/2021 Maintenance/Ownership: State
Bridge B4-5:	Girder and floorbeam system - 1959 Structure No: 203200B4-511202 Length: 132' Weight Limit: 0 Facility Carried: RAILROAD Structure Type: RIVETED TWO GIRDER Features Intersected: VT RR OVER BR US 4

Historic Projects Unknown, Retreatment, Resurface, Bituminous Mix, Skiny Mix, Bituminous Seal, Concrete, Reclaimed Base and Bituminous Concrete, Surface Treated Gravel, Plant Mix, Reclaimed Base and Bituminous Concrete	Functional Class 1 - Interstate System, 2 - Other Freeways and Expressways, 3 - Principal Arterial, 4 - Minor Arterial, 5 - Major Collector, 6 - Minor Collector	Curves Left, Right, Grades (up/down), Road Widths (ft)	Traffic Counters Continuous (CTC), Weigh-In-Motion (WIM), Short-Term, Scheduled, Short-Term, Unscheduled	Crash Locations Fatal, Injury, Property Damage Only, Unknown Crash Type, High Crash Locations (HCL's)	Mileage by Functional Class By Sheet 3200 3 - other Principal Arterial 0.997	Mileage by Town By Sheet RUTLAND TOWN - 8004-1120 0.997 of 0.997	DISTRICT 3	TOWN RUTLAND TOWN	Date: 09/25/23	ROUTE BUS-4 ETE mileage: 1.432 to 2.429
Page Total Mileage: 0.997 mi						Page Total Mileage: 0.997 mi				

For More Information Contact - Vermont Agency of Transportation, Policy, Planning and Intermodal Development Division - Mapping Section, 219 North Main Street, Barre, VT 05641 Telephone: 802-828-2600.