DISTRICT TOWN ROUTE DRAFT Route Log and Progress Chart Please Note: Errors and Omissions May Exist. **ROYALTON, BETHEL,** I-89 Contact the VTrans Mapping Section with questions or concerns. **RANDOLPH** Base Map SHARON SOUTH 1 in = 0.9 milesStick Diagram STRUCTURE DESCRIPTIONS Town Center Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps Bridge <mark>26-1</mark>: Culvert - 1969 Bridge <mark>22</mark>: Culvert - 1969 ++++++ Railroad Crossings Structure No. 30008926-114161 Structure No. 300089002214161 Primary Structures Length: 14' Length: 6' Under Clearance: 12.0' Under Clearance: 6.0' Secondary Structures Weight Limit: 0 Weight Limit: 0 Divided State Highway Facility Carried: 189 Facility Carried: I89 Structure Type: RC BOX Structure Type: CGMPP State Highway Features Intersected: BROOK Features Intersected: LAND ACCESS ROAD Divided Town Highway Inspection Date: 11/2019 Inspection Date: 5/2022 ——— Town Highway Maintenance: State Maintenance: State Streams (Hydraulic Structure) Town Boundary Bridge 26-2: Bridge 23: --- District Boundaries Frame - 1968 Culvert - 1969 o - o - State/Town Highway Change Structure No. 200089002314162 Structure No. 30008926-214161 --- Divided Highway Limits Length: 21' Length: 6' Height: 100.0' Under Clearance: 6.0' ---- Ghost Section Boundary Width: 38.0' Weight Limit: 0 ----- Federal Urban Area Limits Under Clearance: 14.0' Facility Carried: I89 Structure Type: CGMPP Weight Limit: 0 Scale: 1 INCH = 2,000 FEET Facility Carried: I 89 ML Features Intersected: BROOK Structure Type: RC BOX Inspection Date: 5/2022 Features Intersected: I 89 OVER TH NO 36 Maintenance: State Inspection Date: 5/2022 Travellane Maintenance/Ownership: State Frame - 1968 Roadway Structure No. 200089002714162 Unknown 23-01: Road Widths Lane Count Length: 21' Height: 100.0' Unknown 5" Crushed Stone Base Course Structure No. 30008923-114161 Structure Type: Unknown Width: 38.0' Subbase Under Clearance: 14.0' Bridge 23-2: Weight Limit: 0 Culvert - 1969 Facility Carried: I 89 ML Curves Structure No. 30008923-214161 Structure Type: RC BOX Features Intersected: I 89 OVER TH NO 32 Length: 8' Under Clearance: 10.0' Inspection Date: 5/2022 Weight Limit: 0 Facility Carried: I89 Maintenance/Ownership: State Grades Structure Type: RC BOX Bridge 28: Features Intersected: BROOK Unknown **Guardrails** Inspection Date: 11/2019 Structure No. 2014040D2814041 Structure Type: Unknown Maintenance: State Inspection Date: 5/2022 **Rumblestrips** Bridge 23-3: Culvert - 1969 Structure No. 30008923-314161 Under Clearance: 10.0' Weight Limit: 0 Facility Carried: 189 Structure Type: RC BOX Features Intersected: BROOK Inspection Date: 11/2019 Maintenance: State Historic Projects 1984: IR 089-1(50 Frame - 1968 Structure No. 200089002414162 Length: 21' Height: 100.0' Width: 38.0' Under Clearance: 14.0' Weight Limit: 0 Facility Carried: I 89 ML Structure Type: RC BOX Features Intersected: I 89 OVER TH NO 6 Inspection Date: 5/2022 Maintenance/Ownership: State District 4 - DMF Maintenance Royalton Garage District 4 - DMF Maintenance Randolph Garage **Maintenance Garage** Bridge 24-1: Culvert - 1969 Structure No. 30008924-114161 Length: 10' Speed Zone Under Clearance: 6.0' Weight Limit: 0 Facility Carried: I89 **Functional Class** Structure Type: RC BOX Features Intersected: CATTLE PASS Inspection Date: 11/2019 (National Highway System Maintenance: State Bridge 25: Frame - 1968 **Limited Access Highway** Structure No. 200089002514162 Length: 21' Height: 100.0' Interstate Or Divided Highway Width: 38.0' **Customer Service Level** Under Clearance: 14.0' Weight Limit: 0 Facility Carried: I 89 ML **Traffic Counters** Structure Type: RC BOX Features Intersected: I 89 OVER TH NO 35 Inspection Date: 5/2022 7318 Maintenance/Ownership: State 6814 6480 Stringer/multi-beam or girder - 1968 6035 5477 Structure No. 200089026S14162 **AADT** Length: 917' 8047 8355 Height: 100.0' 2019 Width: 30.0' Under Clearance: 16.0' Weight Limit: 0 Facility Carried: I 89 ML Structure Type: 6 SPAN CONT GIRDER Features Intersected: I 89 OVER WR+NECR+107 (Incomplete) 2023 Surface: Bituminous Inspection Date: 5/2022 Maintenance/Ownership: State

Mileage by Functional Class By Sheet

Mileage by Town By Sheet

9.0 of 130.254

Page Total Mileage: 9.0 mi

DISTRICT

ROUTE

ETE mileage:

18.0 to 27.0

Date: 09/28/23

3 of 15

TWN mileage:

18.0 to 27.0

TOWN

ROYALTON, BETHEL,

RANDOLPH

9.000 ETE - I089-0000S

Page Total Mileage: 9.000 mi

Functional Class

1 - Interstate 3 - Principal 5 - Major Collector

2 - Other 4 - Minor Arterial

Traffic Counters

Continuous (CTC)

♠ Short-Term, Scheduled

△ Short-Term, Unscheduled

Left (percent) grade up grade down

Road Widths

Crash Locations

High Crash Locations (HCL's)

HCL No. 201 - 300 (21 - 30)

1 - 100 (1 - 10) 301 - 400 (31 - 40)

Sections (& Intersections)

 Weigh-In-Motion (WIM)
 ■ Injury
 ■ Unknown Crash Type

■ Fatal ☐ Property Damage Only 89-1 1 - Interstate

Crash Locations 2021

Retreatment Bituminous Macadam

Unknown

Resurface

■ Bituminous Mix

Skinny Mix Concrete

ःःः Bituminous Seal **胚** Gravel

2019

Bituminous Concrete
Bituminous Macadam

Surface Treated
Gravel

Cold Plane and
Bituminous Concrete

Concrete

Concrete

Bituminous Wacadam

Plant Mix

Reclaimed Base and
Bituminous Concrete

Historic Projects