DISTRICT TOWN ROUTE DRAFT Route Log and Progress Chart Please Note: Errors and Omissions May Exist. HARTLAND, WINDSOR I-91 Contact the VTrans Mapping Section with questions or concerns. Base Map WINDSOR WEATHERSFIELD z >SOUTH 1 in = 0.5 milesStick Diagram STRUCTURE DESCRIPTIONS Town Center Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps Bridge 33S: Stringer/multi-beam or girder - 2013 +++++ Railroad Crossings Structure No. 200091033S14232 Primary Structures Length: 645' Height: 100.0' Secondary Structures Width: 38.0' Divided State Highway Under Clearance: 66.0' State Highway Weight Limit: 0 Facility Carried: I 91 ML Divided Town Highway Structure Type: 4 SP CONCRETE GIRDER ——— Town Highway Features Intersected: I 91 OVER VT 44 MILLB Streams (Hydraulic Structure) Inspection Date: 5/2022 Town Boundary Maintenance/Ownership: State --- District Boundaries o - o - State/Town Highway Change Bridge 33-3: Culvert - 1966 --- Divided Highway Limits Structure No. 30009133-314231 ---- Ghost Section Boundary Length: 8' ----- Federal Urban Area Limits Under Clearance: 8.0' Weight Limit: 0 Scale: 1 INCH = 2,000 FEET Facility Carried: I91 Structure Type: CGMPP ALUM SLEEVE 58 | | | | | Features Intersected: BROOK Inspection Date: 12/2019 Travellane Maintenance: State Roadway Road Widths Lane Count Stringer/multi-beam or girder - 1965 Two 2 1/2" Cr. Stone Base Course Structure No. 200091034S14232 Length: 168' Subbase Height: 100.0' Width: 30.0' Under Clearance: 17.0' Curves Weight Limit: 0 Facility Carried: I 91 ML Structure Type: 3 SP CONT ROLLED BM Features Intersected: I 91 OVER TH NO 5 Grades Surface: Bituminous Inspection Date: 5/2022 Maintenance/Ownership: State **Guardrails** Bridge 35S: Stringer/multi-beam or girder - 1965 Structure No. 200091035S14232 **Rumblestrips** Height: 100.0' Width: 38.0' Under Clearance: 14.0' Weight Limit: 0 Facility Carried: I 91 ML Structure Type: WELDED PLATE GIRDER Features Intersected: I 91 OVER TH NO 3 Surface: Bituminous Inspection Date: 5/2022 Maintenance/Ownership: State Historic Projects Bridge 35-1: Culvert - 1966 Structure No. 30009135-114231 1985: IR 091-1(48) Length: 8' Under Clearance: 9.0' Weight Limit: 0 Facility Carried: I91 Structure Type: CGMPP Features Intersected: BASHON BRK Inspection Date: 12/2019 Maintenance: State District 4 - DMF Maintenance Windsor Garage Unknown 36: **Maintenance Garage** Unknown Structure No. 200113058A14092 Structure Type: Unknown Speed Zone Culvert (Arch) - 1965 Structure No. 20009136-114092 **Functional Class** Length: 24' Height: 100.0' Weight Limit: 0 (National Highway System Facility Carried: I 91 ML Structure Type: RC ARCH Features Intersected: LULLS BROOK Inspection Date: 5/2022 Limited Access Highway Maintenance/Ownership: State Unknown: Interstate Or Divided Highway **Customer Service Level** Structure No. 201409D37S14091 Structure Type: Unknown Traffic Counters Bridge 37-1: Culvert - 1966 Structure No. 30009137-114091 7219 8778 Length: 13' Under Clearance: 8.0' 6710 8173 Weight Limit: 0 Facility Carried: I91 5943 7239 Structure Type: CGMPPA **AADT** Features Intersected: BROOK 7924 7129 9652 Inspection Date: 12/2019 2019 Maintenance: State 2018 (Incomplete) 2023