## **DISTRICT TOWN ROUTE DRAFT Route Log and Progress Chart** Please Note: Errors and Omissions May Exist. I-89 WATERBURY, MIDDLESEX, Contact the VTrans Mapping Section with questions or concerns. **MONTPELIER** Base Map MIDDLESEX MORETOWN WATERBURY SOUTH 1 in = 2,000 feetStick Diagram STRUCTURE DESCRIPTIONS Town Center Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps, Bridge 45-5: Culvert - 1991 Bridge 43S: Stringer/multi-beam or girder - 1960 ++++++ Railroad Crossings Structure No. 30008945-512181 Structure No. 200089043S12102 Primary Structures Length: 205' Length: 8' Height: 100.0' Under Clearance: 7.0' Secondary Structures Width: 32.0' Weight Limit: 0 Divided State Highway Facility Carried: I89 Under Clearance: 14.0' Structure Type: SEGMENTAL RC BOX State Highway Weight Limit: 0 Facility Carried: I 89 ML Features Intersected: BROOK Divided Town Highway Structure Type: 3 SP CONT ROLLED BM Inspection Date: 10/2019 ——— Town Highway Features Intersected: I 89 OVER US 2 Maintenance: State Streams (Hydraulic Structure) Surface: Bituminous Town Boundary Inspection Date: 5/2022 Bridge 45-8: --- District Boundaries Culvert - 1960 Maintenance/Ownership: State o - o - State/Town Highway Change Structure No. 30008945-812181 --- Divided Highway Limits Length: 14' Culvert - 1960 Under Clearance: 12.0' ---- Ghost Section Boundary Structure No. 30008943-112101 Weight Limit: 0 ----- Federal Urban Area Limits Length: 12' Facility Carried: I89 Structure Type: RC BOX Under Clearance: 8.0' Scale: 1 INCH = 2,000 FEET Weight Limit: 0 Features Intersected: LAND ACCESS ROAD Facility Carried: I89 Inspection Date: 10/2019 Structure Type: CGMPPA Maintenance: State Features Intersected: BROOK Travellane Inspection Date: 11/2019 Maintenance: State Roadway **Road Widths** Lane Count Bridge 43-2: 5" Crushed Stone Base Course Culvert - 1960 Structure No. 30008943-212101 Subbase Length: 6' Under Clearance: 6.0' Weight Limit: 0 Curves Facility Carried: 189 Structure Type: ACCGMPP Features Intersected: BROOK Inspection Date: 11/2019 Grades Maintenance: State Unknown 44: **Guardrails** Unknown Structure No. 200284005512102 Structure Type: Unknown **Rumblestrips** Culvert - 1960 Structure No. 30008944-212101 **Speed Zone** Length: 7' Under Clearance: 5.0' Weight Limit: 0 Curves: Head-on, FTC6 Facility Carried: I89 Structure Type: CGMPPA STEEL SLEEVED Features Intersected: BROOK Inspection Date: 11/2019 Curves: Overturn, FTC7 Maintenance: State Bridge 44-4: Curves: Run-off Road, FTC8 Culvert - 1960 Structure No. 20008944-412102 Length: 31' Height: 100.0' Curves: Fixed Object, FTC9 Weight Limit: 0 Facility Carried: I 89 ML Structure Type: TWIN CELL RC BOX Curves: Night Run-off Road, FTC10 Features Intersected: GREAT BROOK Inspection Date: 5/2022 Maintenance/Ownership: State Interstate: Overturn, FTC11 Stringer/multi-beam or girder - 1960 Structure No. 200089045S12102 Tangents: Head-on, FTC12 Length: 117' Height: 100.0' Width: 42.0' Under Clearance: 16.0' Tangents: Overturn, FTC13 Weight Limit: 0 Facility Carried: I 89 ML Structure Type: 3 SPAN ROLLED BEAM Tangents: Run-off Road, FTC14 Features Intersected: I 89 OVER MDLSX S.H. Surface: Bituminous Inspection Date: 5/2022 Maintenance/Ownership: State Risk Primary Risk Bridge 45-1: Culvert - 1960 Structure No. 30008945-112101 Length: 7' Medium Risk Weight Limit: 0 Facility Carried: I89 Low Risk Structure Type: CGMPP Minimal Risk Features Intersected: BROOK Inspection Date: 12/2021 Not a Focus Facility Maintenance: State Bridge 45-2: Culvert - 1993 Structure No. 30008945-212101 Length: 8' Under Clearance: 6.0' Weight Limit: 0 Facility Carried: I89 Structure Type: SEGMENTAL RC BOX Features Intersected: BROOK Inspection Date: 10/2019 Maintenance: State 11637 13334 12446 12415 10835 11591 9321 8193

12428

Mileage by Town By Sheet

10924

Mileage by Functional Class By Sheet

**AADT** 

2019

2018 10835

**Historic Projects** 

12796

**Curves Grades** 

Traffic Counters

**Crash Locations** 

**Functional Class**