DISTRICT TOWN ROUTE DRAFT Route Log and Progress Chart Please Note: Errors and Omissions May Exist. **ROYALTON, BETHEL,** I-89 Contact the VTrans Mapping Section with questions or concerns. **RANDOLPH** POMFRET Base Map BETHEL 1 in = 0.9 miles Stick Diagram STRUCTURE DESCRIPTIONS Town Center Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps, Bridge <mark>26-1</mark>: Culvert - 1969 Bridge <mark>22</mark>: Culvert - 1969 ++++++ Railroad Crossings Structure No. 30008926-114161 Structure No. 300089002214161 Primary Structures Length: 14' Length: 6' Under Clearance: 12.0' Under Clearance: 6.0' Secondary Structures Weight Limit: 0 Weight Limit: 0 Divided State Highway Facility Carried: 189 Facility Carried: I89 Structure Type: RC BOX Structure Type: CGMPP State Highway Features Intersected: LAND ACCESS ROAD Features Intersected: BROOK Divided Town Highway Inspection Date: 11/2019 Inspection Date: 5/2022 ——— Town Highway Maintenance: State Maintenance: State Streams (Hydraulic Structure) Town Boundary Bridge 23: Bridge 26-2: --- District Boundaries Frame - 1968 Culvert - 1969 o - o - State/Town Highway Change Structure No. 30008926-214161 Structure No. 200089002314162 --- Divided Highway Limits Length: 21' Length: 6' Height: 100.0' Under Clearance: 6.0' ---- Ghost Section Boundary Width: 38.0' Weight Limit: 0 ----- Federal Urban Area Limits Under Clearance: 14.0' Facility Carried: I89 Structure Type: CGMPP Weight Limit: 0 Scale: 1 INCH = 2,000 FEET Facility Carried: I 89 ML Features Intersected: BROOK Structure Type: RC BOX Inspection Date: 5/2022 Features Intersected: I 89 OVER TH NO 36 Maintenance: State Inspection Date: 5/2022 Travellane Maintenance/Ownership: State Frame - 1968 Roadway Structure No. 200089002714162 Unknown 23-01: **Road Widths** Lane Count Unknown Length: 21' 5" Crushed Stone Base Cours Structure No. 30008923-114161 Height: 100.0' Structure Type: Unknown Width: 38.0' Subbase Under Clearance: 14.0' Bridge 23-2: Weight Limit: 0 Culvert - 1969 Facility Carried: I 89 ML Curves Structure No. 30008923-214161 Structure Type: RC BOX Features Intersected: I 89 OVER TH NO 32 Length: 8' Under Clearance: 10.0' Inspection Date: 5/2022 Weight Limit: 0 Facility Carried: I89 Grades Maintenance/Ownership: State Structure Type: RC BOX Bridge 28: Features Intersected: BROOK Unknown **Guardrails** Inspection Date: 11/2019 Structure No. 2014040D2814041 Structure Type: Unknown Maintenance: State Inspection Date: 5/2022 **Rumblestrips** Bridge 23-3: Culvert - 1969 Structure No. 30008923-314161 **Speed Zone** Under Clearance: 10.0' Weight Limit: 0 Facility Carried: 189 Curves: Head-on, FTC6 Structure Type: RC BOX Features Intersected: BROOK Inspection Date: 11/2019 Maintenance: State Curves: Overturn, FTC7 Frame - 1968 Curves: Run-off Road, FTC8 Structure No. 200089002414162 Length: 21' Height: 100.0' Width: 38.0' Curves: Fixed Object, FTC9 Under Clearance: 14.0' Weight Limit: 0 Facility Carried: I 89 ML Curves: Night Run-off Road, FTC10 Structure Type: RC BOX Features Intersected: I 89 OVER TH NO 6 Inspection Date: 5/2022 Maintenance/Ownership: State Interstate: Overturn, FTC11 Bridge 24-1: Culvert - 1969 Tangents: Head-on, FTC12 Structure No. 30008924-114161 Length: 10' Under Clearance: 6.0' Weight Limit: 0 Tangents: Overturn, FTC13 Facility Carried: I89 Structure Type: RC BOX Features Intersected: CATTLE PASS Tangents: Run-off Road, FTC14 Inspection Date: 11/2019 Maintenance: State Bridge 25: Risk Frame - 1968 Primary Risk Structure No. 200089002514162 Length: 21' Height: 100.0' Width: 38.0' Medium Risk Under Clearance: 14.0' Low Risk Weight Limit: 0 Facility Carried: I 89 ML Minimal Risk Structure Type: RC BOX Features Intersected: I 89 OVER TH NO 35 Not a Focus Facility Inspection Date: 5/2022 Maintenance/Ownership: State Stringer/multi-beam or girder - 1968 Structure No. 200089026N14162 Length: 917' Height: 100.0' Width: 30.0' Under Clearance: 18.0' Weight Limit: 0 Facility Carried: I 89 ML Structure Type: 6 SPAN CONT GIRDER 7427 6826 Features Intersected: I 89 OVER WR+NECR+107 Surface: Bituminous 6915 6356 Inspection Date: 5/2022

8337

16100

6568

Maintenance/Ownership: State

6125

8166

15800

AADT